


Process Color Codes KEIM Restauro USA



	FUS-R716 CMYK: C:27 M:45 Y:40 K:13 RGB: R:147 G:119 B:110
	FUS-R715 CMYK: C:33 M:37 Y:34 K:14 RGB: R:141 G:128 B:123
	FUS-R714 CMYK: C:20 M:21 Y:24 K:4 RGB: R:191 G:183 B:172
	FUS-R713 CMYK: C:14 M:23 Y:31 K:3 RGB: R:202 G:185 B:160
	FUS-R712 CMYK: C:15 M:17 Y:19 K:2 RGB: R:206 G:199 B:190
	FUS-R711 CMYK: C:29 M:43 Y:37 K:14 RGB: R:143 G:120 B:115
	FUS-R710 CMYK: C:22 M:21 Y:22 K:4 RGB: R:186 G:181 B:174
	FUS-R709 CMYK: C:18 M:25 Y:28 K:4 RGB: R:191 G:176 B:161
	FUS-R708 CMYK: C:16 M:32 Y:39 K:5 RGB: R:187 G:161 B:134
	FUS-R707 CMYK: C:16 M:17 Y:24 K:2 RGB: R:204 G:196 B:179
	FUS-R706 CMYK: C:18 M:27 Y:36 K:6 RGB: R:184 G:167 B:142
	FUS-R705 CMYK: C:23 M:21 Y:24 K:4 RGB: R:183 G:178 B:170
	FUS-R704 CMYK: C:31 M:50 Y:47 K:18 RGB: R:130 G:101 B:91
	FUS-R703 CMYK: C:29 M:46 Y:40 K:15 RGB: R:140 G:113 B:106
	FUS-R702 CMYK: C:35 M:42 Y:38 K:18 RGB: R:129 G:113 B:109
	FUS-R701 CMYK: C:33 M:16 Y:25 K:4 RGB: R:186 G:179 B:170